

DEPARTMENT OF TRANSPORTATION**DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-013424**Date Inspected:** 22-Apr-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A			CWI Present:	Yes	No	
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006			Component:	OBG		

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

TRIAL ASSEMBLY YARD

ULTRASONIC INSPECTION

OBG SEGMENT 8BW

ABF Request No: 04222010-1

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Rejectable indications were observed. Inspection was carried out on repair areas. Weld identification numbers were.

CA049-004 (8BW, DP to EP, C.W side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication. For more information refer the ABF /CT report dated on 04/22/2010.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

ULTRASONIC INSPECTION

OBG SEGMENT 7DE

ABF Request No: 04222010-2

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Rejectable indications were observed. Inspection was carried out on repair areas. Weld identification numbers were.

CA042-004 (7DE, DP to EP, B.P side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication. For more information refer the ABF /CT report dated on 04/22/2010.

MAGNETIC PARTICLE INSPECTION

OBG SEGMENT 7DE

ABF Request No. 04222010-2

This QA Inspector Witnessed ABF personal performing Magnetic particle Testing (MT) on weld between edge panel and deck panel (bike path side) of the OBG segment 7DE. Inspection was carried out on repair areas. Weld identification number was.

CA042-004 (7DE, DP to EP, B.P side)

No relevant indications were observed.

MAGNETIC PARTICLE INSPECTION

OBG SEGMENT 8BW

ABF Request No. 04222010-1

This QA Inspector Witnessed ABF personal performing Magnetic particle Testing (MT) on weld between edge panel and deck panel (Counter weight side) of the OBG segment 8BW. Inspection was carried out on repair areas. Weld identification number was.

CA049-004 (8BW, DP to EP, C.W side)

No relevant indications were observed.

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By: Utekar,Shrikant

Quality Assurance Inspector

Reviewed By: Dawson,Paul

QA Reviewer